

Revised 07/03

**CORRES CONTROL  
INCOMING LTR NO**

00809 RFO3

**DUE DATE  
ACTION**

Bill Owens, Governor  
Douglas H. Benevento, Executive Director

Dedicated to protecting and improving the health and environment of the people of Colorado

4300 Cherry Creek Dr S  
Denver, Colorado 80246-1530  
Phone (303) 692-2000  
TDD Line (303) 691-7700  
Located in Glendale, Colorado

Laboratory and Radiation Services Division  
8100 Lowry Blvd  
Denver, Colorado 80230-6928  
(303) 692-3090

<http://www.cdphe.state.co.us>

RECEIVED  
STATE OF COLORADO

2003 AUG 27 P 3:11

CORRESPONDENCE  
CONTROL



Colorado Department  
of Public Health  
and Environment

DIST	LTR	ENC
BERARDINI, J. H.	X	
BOGNAR, E. S.	X	
CROCKETT, G. A.		
DECK, C. A.	X	
DEGENHART, K. R.		
DIETER, J. J.		
DIETERLE, S. E.		
FERRERA, D. W.	X	
FERRI, M. S.		
GIACOMINI, J. J.		
ISOM, J. H.		
LINDSAY, D. C.	X	
LONG, J. W.		
LYLE, J. L.		
MARTINEZ, L. A.	X	
NAGEL, R. E.	X	
NORTH, K.		
PARKER, A. M.	X	
RODGERS, A. D.		
SHELTON, D. C.	X	
SPEARS, M. S.		
TRICE, K. D.		
TUCKER, N. B.	X	
WILLIAMS, J. L.		
PARSONS, D.	X	
BUTLER, L.	X	
WIEMELT, K.	X	
NESTA, S.	X	
BROOKS, L.	X	

COR. CONTROL	X
ADMIN. RECORD	X
PATS/130	

Reviewed for Addressee  
Corres Control RFP

8/27/03  
Date By

Ref Ltr #

DOE ORDER #

NONE

DOCUMENT CLASSIFICATION  
REVIEW WAIVER PER  
CLASSIFICATION OFFICE

August 22, 2003

Mr Joseph Legare  
Assistant Manager for Environment and Stewardship  
U S Department of Energy, Rocky Flats Field Office  
10808 Highway 93, Unit A  
Golden, CO 80403-8200

**RE: B865 Facility Disposition RSOP Notification**

Dear Mr Legare

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed your August 14, 2003 letter notifying us that the Facility Disposition RSOP will be utilized during the demolition of B865. We hereby agree that B865 may be demolished utilizing the Facility Disposition RSOP, with the following restrictions

- 1 The activity to be performed per this notification includes the superstructure and not the floor/slab of B865. The demolition of the floor/slab will be performed after submittal of a separate RSOP Notification.
- 2 It must be recognized that even though the beryllium has been fixed, the superstructure of B865 will still need to be managed as beryllium contaminated waste, as indicated in the PDSR.


If you have any questions regarding this correspondence please contact me at (303) 692-3367 or David Kruchek at (303) 692-3328.

Sincerely,

Steven H. Gunderson  
RFCA Project Coordinator

cc Steve Tower, DOE  
Tim Rehder, EPA  
Duane Parsons, KH  
Lane Butler, KH

Karen Wiemelt, KH  
Dave Shelton, KH  
Steve Nesta, KH  
Administrative Records Building T1306



B865-A-000061